

Change Notice



M Series

Changes to Location & Production for Specific M Series Products

Type of Change:

- ☐ Engineering ☐ Part Number
☐ Product ☒ Appearance

There will be revisions to the production and manufacture location for specific M Series products. Previously, the lot code on the switch body had a dot mark above the first digit, but now the dot mark will be above the second digit. The shipping box for these switches had "CHINA FACTORY" on the side, but will be replaced with "PHILIPPINES FACTORY." These changes will apply only to the M Series part numbers listed and sold/shipped by NKK Switches of America. Effected part numbers follow on pages 2 and 3.

	Lot Number	Shipping Box
Before Changes	Dot Mark Above First Digit  Enlarged to Show Detail	 "CHINA FACTORY" printed on side of box
After Changes	Dot Mark Above Second Digit  Enlarged to Show Detail	 "PHILIPPINES FACTORY" printed on side of box

Notes

- There are no changes to the switches' dimensions or specifications.
- The location of the Lot Number on switch case may vary depending on the part number.
- The size and shape of the Shipping Box may vary depending on the part number.
- Current orders for products originating in China Factory (Country of Origin, COO) will **not** be changing to Philippines Factory.
- Contact the factory if more details are needed.

Effective Dates

Changes in location and production for specific M Series switches will be effective after current inventory of the products from China (Country of Origin, COO) is depleted.

NKK
SWITCHES

www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

Change Notice

M Series

Changes to Location & Production for Specific M Series Products

EFFECTED PART NUMBERS TO BE TRANSFERRED TO THE PHILIPPINES FACTORY AS OF 8/28/25

MN11B2B1W01	MN12LL1W01	MN12SS1W03	MN13SS1G40	MN18SS1G03
MN11B2B1W03	MN12LL1W03	MN12SS1W06	MN13SS1W01	MN18SS1G40
MN11B2B3G01	MN12LL3G01	MN12SS2W13	MN13SS1W03	MN18SS1W01
MN11B2B3W01	MN12LL3W01	MN12SS4W01	MN13SS1W06	MN18SS1W03
MN11BB1W01	MN12S2A1W03	MN12TNW01	MN13SS4G01-N853	MN18SS2W13
MN11ES1W01	MN12S2A2A30/CUL	MN12TXG13	MN13TNW01	MN18TJG02
MN11LL1W01	MN12S2A2G13	MN12TXG13-DA	MN13TXW41	MN18TJW01
MN11LL3W03	MN12S2A2G40	MN12TXG30	MN13WBW01	MN18TXG13
MN11S2A1W01	MN12S2A2W13	MN12TXG30-DA	MN15B2B1G01	MN18TXG13-DA
MN11S2S1W01	MN12S2A2W30	MN12TXG41	MN15B2B1W01	MN18TYW01
MN11S3A1W03	MN12S2A2W40	MN12TXW13	MN15B2B3G01	MN18TZW13
MN11SD3W01	MN12S2D3G01	MN12TXW30	MN15B2B3W01	MN18WBW01
MN11SS1G01	MN12S2S1W01	MN12TXW41-DA	MN15BB1G06	MN19B2B1G01
MN11SS1W01	MN12S3A1W01	MN12WBG01	MN15S2S1W01	MN19B2B1W01
MN11SS1W03	MN12S3A2G13	MN12WBW01	MN15SS1G03	MN19BB1W01
MN11SS4W01	MN12S3S2W40	MN12X023	MN15SS1W01	MN19BB1W03
MN12B2B1G01	MN12SA1W03	MN12X024	MN15SS1W03	MN19ES1W03
MN12B2B1G03	MN12SA1W05	MN13B2B1G01	MN18B2B1G01	MN19SS1W01
MN12B2B1W01	MN12SA2A13	MN13B2B1W01	MN18B2B1W01	MN19SS1W03
MN12B2B1W03	MN12SA2W13	MN13B2B1W-01-NA09	MN18B2B1W03	MN19TXG13
MN12B2B3G01	MN12SA2W40	MN13B2B1W03	MN18B2B3G01	MN21ES1W01
MN12B2B3W01	MN12SD3G01	MN13B2B3G01	MN18B2B3W01	MN22B2B1G01
MN12BB1G01	MN12SD3W01	MN13E2D8G01	MN18BB1W01	MN22B2B1W01
MN12BB1W01	MN12SD3W03	MN13E2S1G03	MN18E2D8G01	MN22B2B1W03
MN12EA2G13	MN12SS1G01	MN13ES1W01	MN18E2S1W03	MN22B2B3G01
MN12EA2W13	MN12SS1G02	MN13ES1W01/3	MN18EA1G01	MN22B2B3W01
MN12ES1G01	MN12SS1G03	MN13LL1W01	MN18ES1G40	MN22ES1W01
MN12ES1W01	MN12SS1G40	MN13SA2W03/CUL	MN18ES1W01	MN22LL1W01
MN12ES1W03	MN12SS1W01	MN13SD3G01	MN18SD1W01	MN22LL2W30
MN12LL1G03	MN12SS1W01-N994	MN13SD3W01	MN18SD3G01	MN22LL2W40



www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

Change Notice

M Series

Changes to Location & Production for Specific M Series Products

EFFECTED PART NUMBERS TO BE TRANSFERRED TO THE PHILIPPINES FACTORY AS OF 8/28/25				
MN22LL3W01	MN22TXG13	MN23TJW01	MN26TXG13	M2011SS1W01-N983
MN22S2A1W01	MN22TXG13-DC	MN23TXG41	MN27E2A1W01	M2012ES1W01-N984
MN22S2A2G40	MN22TXG15/108	MN24B2B1G01	MN28B2B1G01	M2012S2A2A30-N978
MN22S2A2W03	MN22TXG30	MN24BB1W01	MN28B2B1W03	M2012SS2W13-235A
MN22S2A2W30	MN22TXW13	MN24SS1G03	MN28SS1G30	M2013SA2W03-N985
MN22S2A2W40/CUL	MN22TXW30	MN24SS1W01	MN28SS1W01	M2013TXW41-N988
MN22S3D3W01	MN22TXW30/CUL	MN24SS1W03	MN28SS1W03	M2018TJG01-N982
MN22SD3W01	MN22TXW41	MN24TJW01	MN28SS2W40	M2018TXW13-235A
MN22SS1G03	MN22WBW01	MN24X002	MN28TJW01	M2022S2A2W40-N981
MN22SS1W01	MN23B2B1G01	MN25B2B1G01	MN28TXG41	M2022TXW13-235A
MN22SS1W03	MN23B2B3W03/CUL	MN25S3A2G13	MN28WBW01	M2022TXW30-N980
MN22SS2W30	MN23LL1W01	MN25SS1A06	MN29B2B1G01	M2023B2B3W03-N979
MN22SS4G03	MN23SS1G03	MN25SS1W01	MN29ES1W01	—
MN22SS4W03	MN23SS1W01	MN25TXG13-DH	MN29TXG13-DC	—
MN22TJW01	MN23SS1W03	MN26SS1W01	MN29TXW13	—



www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435