

Change Notice

FR01 Rotaries

Change of Font on FR01 Dial Actuator

Type of Change:

- Engineering Part Number
- Product Appearance

All models of FR01 DIP rotary switches that have the dial actuators will have a change to the font on the actuators. This change will effect both standard and custom products for this series. The tables below display the part numbers that will be effected, and the older font as well as the new one that will be replacing it.



Standart Part Numbers Effected by Change of Font			
FR01SR10P	FR01SC10P	FR01SR16P	FR01SC16P

Positions	Before Change	After Change
Binary Code Decimal	0 1 2 3 4 5 6 7 8 9	0 1 2 3 4 5 6 7 8 9
Binary Code Hexadecimal	A B C D E F 0 1 2 3 4 5 6 7 8 9	A B C D E F 0 1 2 3 4 5 6 7 8 9

Notes

There are no changes to the switches' dimensions or specifications. Contact the factory if more details are needed.

Effective Date

Changes to the font on the FR01 dial actuators will be effective with June 2014 production.



<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435