Change Notice

Changes to Location of Production for S Toggles & SW Rockers

Type of Change:

□ Engineering □ Part Number ☐ Product ☑ Appearance

I. The location of production will change for specific S Toggles and SW Rockers from the Japan factory to the Philippines factory. The factory name and place of manufacture will no longer appear on the bottom of switches, and the lot number on the side of switch cases will have a dot mark above the second digit. The box in which the switches are packaged for shipping will read "PHILIPPINES FACTORY" instead of "JAPAN FACTORY." All of these modifications will apply to standard, custom and UL/CSA approved products.



Changes for S Toggles & SW Rockers

Example: S3A	Bottom of Switch	Lot Number	Shipping Box
Before Changes	Factory Location and Name on Bottom of Switch Case	Example of Lot Number	
	"Nikkai"	66	"JAPAN FACTORY" printed on side of box
After Changes	Factory Location and Name Removed	Example of Lot Number with Dot Mark Above Second Digit	
	"Nikkai" Removed "Nikkai" Removed	66	"PHILIPPINES FACTORY" printed on side of box

Notes

There are no changes to the switches' dimensions or specifications.

The location of the Lot Number on switch case may vary depending on the part number.

Contact the factory if more details are needed.

	SW Rockers			
S1A	S2A	S3A	S5AW	SW3001A
S1AL	S2AL	S3AL	S8AW	SW3002A
S1AW	S2AW	S3AW	S9AW	SW3003A
S1F	S2F	S3F		

Effective Dates

Changes to S Toggles and SW Rockers will be effective January 2017.



http://www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

Change Notice

Change to UL Factory Code for S Toggles

Type of Change:

□ Engineering□ Part Number□ Product☑ Appearance



2. S Toggles with UL approval, both standard and custom, will have a change to the UL factory code. The table below illustrates the modification, followed by the effected part numbers.

Changes for S Toggles

UL Factory Code Change on S Toggles

Before Change

After Change

UL Approval & No Factory Code



UL Approval & Factory Code Added



S Toggles Effected by Factory Code Change					
S1A/U	S2A/U	S3A/U			

Notes

There are no changes to the switches' dimensions or specifications.

The location of the UL code on switch case may vary depending on the part number. Contact the factory if more details are needed.

Effective Dates

Changes to S Toggles UL and factory code will be effective January 2017.



http://www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435