SK & NR01 Series

Changes to Location & Production for SK Antistatic Process Sealed Keylocks & NR01 Rotaries

Type of Change:

□ Engineering □ Part Number
□ Product ☑ Appearance

I. There will be changes for the SK Series Antistatic Process Sealed Keylocks and NR01 Series Rotary Switches. The lot number on the switch body will have a dot mark above the second digit, and the box in which the switches are packaged for shipping will read "PHILIPPINES FACTORY" instead of "JAPAN FACTORY." These revisions will apply to standard and custom products. Effected standard part numbers for SK and NR01 Series are on the table displayed on page 2.



Changes for SK Keylocks & NR01 Rotaries

| | Lot Number | Shipping Box | |
|----------------|---|--|--|
| | Example of Lot Number | | |
| Before Changes | 84 Enlarged to Show Detail | - "JAPAN FACTORY" printed on side of box | |
| After Changes | Example of Lot Number with Dot Mark Above Second Digit 84 Enlarged to Show Detail | "PHILIPPINES FACTORY" printed on side of box | |

Notes

There are no changes to the switches' dimensions or specifications.

The location of the lot number on switch body may vary depending on the part number.

Contact the factory if more details are needed.

Effective Dates

Location and production changes for SK Keylocks and NR01 Rotaries will be effective December 2021.



www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

Change Notice

Changes to Production for SK Antistatic Process Sealed Keylocks

| ☐ Engineering☐ Product | □ Part I ☑ Appe | replacement of the old | er logo with the updated NKK logo. These revision and custom SK Series switches. Effected standard ayed below. |
|---|-----------------|----------------------------|--|
| | | Identificat | tion on Switch |
| | | " IADANI" | Older NKK Logo |

2. Changes to production of the SK Series Antistatic Process Sealed

Keylocks will include the removal of "JAPAN" on the switch body and the

| Before Changes | "JAPAN" on Switch Body | Older NKK Logo |
|----------------|--------------------------------------|------------------|
| After Changes | "JAPAN" on Switch Body Removed | NKK Logo Updated |

Notes

Type of Change:

There are no changes to the switches' dimensions or specifications.

The location of the logo on switch body may vary depending on the part number. Contact the factory if more details are needed.

| | NR01 Series Part Numbers for Change 1 | | | | | | |
|--|---------------------------------------|----------------|----------------|--|--|--|--|
| NR0103ANG13 | NR0103ANG13-1C | NR0103ANG13-2A | NR0103ANG13-2H | | | | |
| NR0104ANG13 | NR0104ANG13-1C | NR0104ANG13-2A | NR0104ANG13-2H | | | | |
| NR0105ANG13 | NR0105ANG13-1C | NR0105ANG13-2A | NR0105ANG13-2H | | | | |
| NR0103ANG13-1A | NR0103ANG13-1H | NR0103ANG13-2C | | | | | |
| NR0104ANG13-1A | NR0104ANG13-1H | NR0104ANG13-2C | | | | | |
| NR0105ANG13-1A | NR0105ANG13-1H | NR0105ANG13-2C | | | | | |
| SK Series Part Numbers for Changes 1 & 2 | | | | | | | |
| SK13AEG13 | SK13AEG30 | SK15AEG13 | SK15AEG30 | | | | |
| SK13AEG13 | SK13AEG30 | SK15AEG13 | SK15AEG30 | | | | |

Effective Date

Production changes for SK Keylocks will be effective December 2021.



www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435