Change Notice

Various Series

Discontinuation of Specific CSA Approved NKK Products with Recommendations for Alternate C-UL Recognized Products

Type of Change:

✓ Engineering☐ Part Number☐ Product☐ Appearance

NKK Switches will be discontinuing a limited number of products with CSA approval. This discontinuation applies to both standard and custom switches with the CSA approval. NKK recommends part numbers with C-UL recognition as alternates for the discontinued devices.

Effected standard and alternate part numbers are listed on the following table.



Specific NKK Products with CSA Approval will be Discontinued

Switch Type		Series	Discontinued Part Numbers with CSA Approval (PN is Representative of Series)	Alternate Part Numbers with C-UL Recognition (PN is Representative of Series)
Toggle	Nonlluminated Toggle	S	S331/C	S331/CUL
Rocker	Nonlluminated Rocker	SW	SW3006A/C	SW3006/CUL
P u		EB	EB2011/C	EB2011/CUL
s h b		JPM	JPM26P/UC	JPM26P/CUL
u t t	Nonlluminated Pushbutton	M2B	M2B25AA5W13/C	M2B25AA5W13/CUL
o n		SB	SB221NC/C	SB221NC/CUL
P u s h b u t t o n	Illuminated Pushbutton	LB	LB15CKW01/C	LB15CKW01/CUL
		UB	UB15KKG016B/C	UB15KKG016B/CUL
		YB	YB15WRKG01/C	YB15WRKG01/CUL
Indicator	Indicator	LB	LB01KW01/C	LB01KW01/CUL

Notes

Standard switches without CSA approval, including custom products, will continue to be available.

Alternate part numbers with C-UL recognition are available for each part number. Add "/CUL" to end of part number to order. See the tables on following pages for specific effected part numbers that NKK Switches America has sold. Contact information is below if more details are needed.

Effective Dates

Orders from the release date of this notice for the discontinued products specified are considered noncancelable, nonreturnable (NCNR). Effective dates for orders of any discontinued products listed and the end sales date are divided into two groups as specified on the following pages.



www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

Discontinuation of Specific CSA Approved NKK Products with Recommendations for Alternate C-UL Recognized Products

Effective Dates

Orders for any of the discontinued products listed below will be accepted through January 21, 2024. The end of sales date is March 31, 2024.

Discontinued Part Numbers Alternate part numbers with C-UL recognition are available for each discontinued part number. Add "/CUL" to end of part number to order.							
JPM26P/UC	S822/C	S821/UC-AT401H	SW3821D/UC				
	S831/C	S822/C-AT401H	SW3831D/UC				
S821/UC	S833/C	S831/UC-AT401H	SW3832D/UC				
S822/UC	S822D/C	S832/C-AT401H	SW3833D/UC				
S831/UC	S831D/C						
S821/C	S833D/C	S821/UC-AT401S	SW3821/UC				
S823/C		S822/C-AT401S	SW3832/UC				
S832/C	S821/UC-AT401A	S831/UC-AT401S	SW3822D/UC				
S821D/C	S822/C-AT401A	S832/C-AT401S	SW3823D/UC				
S823D/C	S831/UC-AT401A						
S832D/C	S832/C-AT401A	SW3821/A/UC	SW3832/A/UC				



www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive · Scottsdale, AZ 85260 · Telephone 480.991.0942 · Fax 480.998.1435

Discontinuation of Specific CSA Approved NKK Products with Recommendations for Alternate C-UL Recognized Products

Effective Dates

Orders for any of the discontinued products listed below will be accepted through June 27, 2024. The end of sales date is December 24, 2024.

Discontinued Part Numbers ternate part numbers with C-UL recognition are available for each discontinued part number. Add "/CUL" to end of part number to order.							
S Toggles	* EB Pushbuttons	YB15WCKW01/UC-CB	LB Illuminated Pushbuttons				
S1A/UC		YB15WRKG01/C	LB15CKG01/UC				
S301F/UC		YB15WRKG01/C-1F24-JF	LB15CKG01/UC-12-JF				
S301F/UC-AT401A	* JPM Pushbuttons	YB15WRKG01/C-2CF24-JB	LB15CKW01/C				
S301F/UC-AT401H		YB15WRKG01/C-5F24-JF	LB15CKW01/C-01-JC				
S301F/UC-AT401S		YB15WRKG01/C-6G-JB	LB15CKW01/UC				
S301F/UC-AT402A	M2B Pushbuttons	YB16KKW01/UC	LB15CKW01/UC-A				
S301F/UC-AT402C	M2B15AA5W30/UC	YB16KKW01/UC-05-FB	LB15WKG01/UC				
S301F/UC-AT402H	M2B15BA5G30/UC	YB16KKW01/UC-5F-JF	LB15WKG01/UC-5D24-JD				
S301T/C	M2B15BA5G30/UC-BA	YB16KKW01/UC-5F05-JF	LB15WKG01/UC-CJ				
S301T/UC	M2B15BA5G30/UC-BC	YB25MKG01/UC	LB15WKW01/UC				
S308/C/328	M2B25AA5W13/C	YB25MKG01/UC-6B-JB	LB15WKW01/UC-5F-JB				
S308T/C		YB25SKW01-1C24-JC/AT4072	LB16WKW01/UC-5F-JF				
S331/C	SB Pushbuttons	YB25WSKW01/UC	LB25CGW01/UC				
S39/C	SB221NC/C	YB26CKW01/UC	LB25CGW01/UC-00-H				
S39/UC	SB4011NCM/C	YB26WRKW01/C	LB25CGW01/UC-H				
S41/C			LB25CKW01/C-01-JC				
S42/C	YB Illuminated Pushbuttons	* UB Illuminated Pushbuttons	LB25CKW01/UC				
	YB15CKW01/UC		LB25SGG01/UC				
SW Rockers	YB15CKW01/UC-BB		LB25SKW01/UC				
SW3006A/C	YB15WCKW01/UC						
SW3006A/UCV	YB15WCKW01/UC-2CF24-JB						

Notes

The list is based on part numbers that NKK Switches America has sold. It does not include part numbers that have not been purchased. However, the discontinuation effects all specified switches with CSA approval.



www.nkkswitches.com • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

^{*} NKK Switches America has not sold any products in this series with CSA mark.