

# Change Notice

# S & SW Series

## Changes to Location & Production for S Toggles & SW Rockers



Changes for S Toggles & SW Rockers

Type of Change:

- Engineering
- Part Number
- Product
- Appearance

I. The location of production will change for specific S Toggles and SW Rockers from the Japan factory to the Philippines factory. The factory name and place of manufacture will no longer appear on the bottom of switches, and the lot number on the side of switch cases will have a dot mark above the second digit. The box in which the switches are packaged for shipping will read "PHILIPPINES FACTORY" instead of "JAPAN FACTORY." All of these modifications will apply to approved standard products (outlined in following tables) as well as custom.

Example: S332	Bottom of Switch	Lot Number	Shipping Box
<b>Before Changes</b>	Factory Name and Location 	Example of Lot Number  63	
<b>After Changes</b>	Factory Name and Location Removed 	Example of Lot Number with Dot Mark Above Second Digit  6 <sup>•</sup> 3	

**Notes**

There are no changes to the switches' dimensions or specifications.  
 The location of the Lot Number on switch case may vary depending on the part number.  
 Contact the factory if more details are needed.

* S Toggles Affected by Production Changes							** SW Rockers
S331	S331F	S331R	S331RN	S331T	S421	S421T	SW3006A
S332	S332F	S332R	S332RN	S332T	S422	S422T	SW3007A
S333	S333F	S333R	S333RN	S333T	S423	S423T	SW3008A
S335		S338R	S338RN	S335T	S425	S425T	
S338		S339R	S339RN	S338T	S428	S428T	
S339				S339T	S429	S429T	

\* Includes UL & CSA approved

\*\* Includes UL & CSA approved; does not include VDE

**Effective Date**

Changes to S Toggles and SW Rockers will be effective October 2016.



<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435

# Change Notice


# S & SW Series

## Change to Logo for S Toggles

Type of Change:

- Engineering
- Part Number
- Product
- Appearance

2. S Toggles will have an updated logo on the side of the switch case with the part number, replacing the older logo. Effected models will include all those with UL/CSA approval, including custom models. The table below illustrates the modification.

Logo Change on Switch Case		
Before Change		After Change
	Example: S421	

S Toggles Effected by Logo Change					
S421	S422	S423	S425	S428	S429
—	S422T	S423T	S425T	S428T	S429T

## Change to UL Factory Code for S Toggles & SW Rockers

Type of Change:

- Engineering
- Part Number
- Product
- Appearance

3. S Toggles and SW Rockers with UL approval will have an additional change on the switch case to include both standard and custom devices. Previously, the UL symbol appeared on the case without a factory code. After the change, the code 080 will appear next to the UL symbol. The table illustrates the difference.

UL Factory Code Change on Side of S Toggles & SW Rockers			
Before Change	After Change		
UL Approval & No Factory Code			
UL Approval & Factory Code Added			

S Toggles Effected by Factory Code Change (UL Approved)					SW Rocker (UL Approved)
S331UL	S331FUL	S331RUL	S331RNUL	S331TUL	
S332UL	S332FUL	S332RUL	S332RNUL	S332TUL	SW3006AUL
S333UL	S333FUL	S333RUL	S333RNUL	S333TUL	
S335UL	S335TUL	—	—	—	
S338UL	S338RUL	S338RNUL	S338TUL	—	
S339UL	S339RUL	S339RNUL	S339TUL	—	

**Notes**

There are no changes to the switches' dimensions or specifications. Contact the factory if more details are needed.

**Effective Date**

Changes to S Toggles and SW Rockers will be effective October 2016.



<http://www.nkkswitches.com> • 1.877.2BUYNKK (228.9655)

7850 East Gelding Drive • Scottsdale, AZ 85260 • Telephone 480.991.0942 • Fax 480.998.1435